



LOW SIGNATURE TASK LIGHT

Operating and Maintenance Instructions

princetontec.com

## Switch Operation

- See Figure 1

- Single press from off to activate IR Low.
- The next press from IR Low activates IR High.
- Press and hold from any mode to activate Red Low.
- The next press from Red Low activates Red High.
- Single press from either IR High or Red High to turn the light off.
- Single press after 3 seconds from any mode to turn light off.

#### installation

- See Figure 2

### **USA- International 1-Year Warranty**

WARRANTY – Princeton Tec warrants this product to be free from defects in workmanship and materials under normal use for one year. This warranty covers all of the component parts of the product except batteries. This warranty does not cover deterioration due to normal wear or damage due to misuse, alteration, negligence, accidents, or unauthorized repair. Princeton Tec will repair or replace parts which are defective in workmanship or materials.

Your authorized Princeton Tec Dealer and Princeton Tec are the only facilities authorized to repair the product. After (3) unsuccessful attempts (within the warranty period) to repair the product, you have the right to elect replacement of the product or a refund of the purchase price less allowance for use of the product. NO INCIDENTAL OR CONSEQUENTIAL DAMAGES ARE INCLUDED IN THIS WARRANTY. (Some states do not allow the exclusion or limitation of incidental or consequential damages, so the above limitations or exclusions may not apply to you.) This warranty gives you specific legal rights, and you may also have other rights which vary from state to state.

Princeton Tec reserves the right to change product specifications without notice.

#### FOR CALIFORNIA RESIDENTS:

*WARNING:* This product contains Bisphenol A (BpA) a chemical known to the State of California to cause birth defects or other reproductive harm.

# Figure 1 – Switch Operation

 Press x1 = IR Low

 Press x1 from IR Low = IR High


 Press + Hold = Red Low

 Press x1 from Red Low = Red High

 Press x1 from IR High or Red High = Off

 Press x1 after 3 seconds in any mode = Off





#### Return Policy

If your light fails to operate, follow these simple steps:

- To send your light in for repair or replacement, first contact Princeton Tec customer service on 1-800-257-9080 to request an RMA number. Please have your light model, date of purchase and a brief description of the fault you are experiencing. No warranty repairs will be accepted without an RMA number.
- Return the light without batteries to: Princeton Tec, PO Box 8057 Trenton NJ 08650. Postage due and freight collect items will not be accepted.
- Upon receipt your light will be processed in about two weeks. Please allow additional time for return transportation from NJ.

Princeton Tec PO Box 8057, Trenton, NJ 08650 Phone: 609-298-9331 Fax: 609-298-9601 www.princetontec.com © 2022 Princeton Tec

